

---

ASOS ERRATA SHEET 1 (for Electronics Technicians)

Engineering Division

W/OSO321:BGM

Errata to ASOS Modification Note 15

**GENERAL**

This errata sheet provides an updated ASOS Modification Index for EHB-11, Volume 2, Section 3.6. This index was to be included with ASOS Modification Note 15.

**PROCEDURE**

Remove and replace the index sheet in EHB-11, Volume 2, Section 3.6 with the attached index.

**EFFECT ON OTHER INSTRUCTIONS**

None.

J. Michael St. Clair  
Chief, Engineering Division

Attachment

W/OSO321:BGMcCormick:713-1834:6/8/94  
WP51 Files: ERRATA15.H11, EHB-11d disk,  
Spellcheck: sol 6/8/94

<i>Issue Date</i>	<i>Org. Code</i>
	W/OSO32

**NATIONAL WEATHER SERVICE  
Engineering Handbook**

<i>Program</i>	<i>Part</i>	<i>Section</i>
EHB-11	03	3.6

MODIFICATION NOTES - AUTOMATED SURFACE OBSERVING SYSTEM

<u>Number</u>	<u>Date of Issue</u>	<u>Title</u>
1	February 23, 1993	Automated Observing System (ASOS) Software Version 1.8
2	March 10, 1993	Liquid Precipitation Accumulation Sensor Cutoff Thermostat Installation
3	March 16, 1993	Installation of External Threshold Detector Power Supply for Setra Model 470
	May 26, 1993	Errata Sheet No. 1 to ASOS Modification Note 3 dated March 16, 1993
4	March 1993	Replacement Battery Box Lid for DCP COMPLETED: ON HOLD BY THE PROGRAM OFFICE
5	April 30, 1993	Firmware Upgrade for Light Emitting Diode Weather Indicator (LEDWI)
6	June 25, 1993	Replacement Data Collection Platform (DCP) Circuit Breaker for the Ceilometer
7	September 9, 1993	Automated Surface Observing System (ASOS) Software Version 2.0
8	September 22, 1993	Wind Sensor Assembly Upgrades
9	September 23, 1993	Temperature/Dewpoint Electronics Enclosure and Aspirator Assembly Replacement
10	April 8, 1994	ACU Software Version 2.1
11	June 8, 1994	Addendum to ASOS Modification Note 10

12		Waiting for certification
13	March 15, 1994	Installation of the 9600-baud modem(s) Model V.3225
14	June 9, 1994	Replacing EPROM on visibility processor board and installing visibility crossare cable guides

<i>Issue Date</i>	<i>Org. Code</i>
	W/OSO32

# NATIONAL WEATHER SERVICE

## Engineering Handbook

<i>Program</i>	<i>Part</i>	<i>Section</i>
EHB-11	03	3.6

14	June 9, 1994	Software Version 2.0 for Voice Processor board 1A2A20
16	June 10, 1994	Installation of Port Sharing Device Memory Board
	May 24, 1994	Errata to ASOS Modification Note 15
17	May 19, 1994	Deactivation of Hygrothermometer Autobalance Module
18	May 18, 1994	Deactivation of Hygrothermometer Fan Fail Circuit

W/OSO321:BGMcCormick:rhz:12/19/94:disk EHB-11.d "errata15.ind" spellchecked